

Dated: 02.02.2021

Description:	Changing internal and external control cable on on/off IP thrusters.
Effective date:	16 th September 2019

Affected Products:	Side-Power Product:	Old Pt.No.:	New Pt.No
	Outside Control Cable SE/IP 1m	4 2000A	4 2000B
	Outside Control Cable SE/IP 9m	4 2004A	4 2004B
	Inside Control Cable SE/IP	4 2001	4 2001B

**We will hold a small amount of legacy stock for replacement requests for your customers. (Not needing in-store repair.)*

The new control cables are designed for extra strength and longer product lifespan.



Internal cable will replace the wiring inside the IP unit.



Outside control cable will replace the current external cables from the IP unit.

For new or in-store repair please install the new internal cable when opening the IP case. This will ensure your future stock will be up-to-date and using the latest technologies.

****END****